

## Radiation Effects of Commercial Resistive Random Access Memories

Dakai Chen, Kenneth LaBel, NASA Goddard Space Flight Center, Greenbelt, MD 20771

Melanie Berg, Edward Wilcox, Hak Kim, Anthony Phan ASRC Space and Defense, Inc., Seabrook, MD 20706

Marco Figueiredo
Orbital Science corp., Greenbelt, MD 20770

Stephen Buchner, Ani Khachatrian, Nicolas Roche Naval Research Laboratory, Washington, DC 29375

## Acknowledgement



- Sponsors:
  - NASA Electronics Parts and Packaging (NEPP)
     Program
  - Defense Threat Reduction Agency (DTRA)
  - National Reconnaissance Office (NRO)
- Adesto and Panasonic for providing technical support

## **Acronyms**



- 1T1R 1 transistor 1 resistor
- BEOL Back-end-of-line
- CBRAM Conductive-bridge random access memory
- CMOS Complimentary metal-oxide-semiconductor
- EEPROM Electrically erasable programmable read only memory
- LCDT Low cost digital tester
- LBNL Lawrence Berkeley National Laboratory
- LET Linear energy transfer
- RAM Random access memory
- ROM Read-only memory

- ReRAM Reduction-oxidation random access memory
- RRAM Resistive Random Access Memory
- SEE Single-event effect
- SEFI Single-event functional interrupt
- SEU Single-event upset
- SOIC Small Outline Integrated Circuit
- TAMU Texas A&M University

## **Motivation**



- Limited availability of radiation tolerant flash memories
- Radiation performance of state-of-the-art flash is generally good but include some weaknesses
- Flash already reaching scaling limits
- Resistive random access memory (RRAM) has shown very good tolerance to radiation\*
- Published radiation test results only from test chips
- A first look at the SEE performance of two commercial production-level RRAMs

<sup>\*</sup> M. J. Marinella, S. M. Dalton, P. R. Mickel, P. E. Dodd, M. R. Shaneyfelt, E. Bielejec, G. Vizkelethy, and P. G. Kotula, "Initial assessment of the effects of radiation on the electrical characteristics of TaO<sub>x</sub> memristive memories," *IEEE Trans. Nucl. Sci.*, vol. 59, pp. 2987 – 2994, Dec. 2012


H. J. Barnaby, S. Malley, M. Land, S. Charnicki, A. Kathuria, B. Wilkens, E. Delonno, and W. Tong, "Impact of alpha particles on the electrical characteristics of TiO<sub>2</sub> memristors," *IEEE Trans. Nucl. Sci.*, vol. 58, pp. 2838–2844, Dec. 2011.

J. S. Bi, Z. S. Han, E. X. Zhang, M. W. McCurdy, R. A. Reed, R. D. Schrimpf, D. M. Fleetwood, M. L. Alles, R. A. Weller, D. Linten, M. Jurczak, and A. Fantini, "The Impact of X-Ray and Proton Irradiation on HfO2/Hf-Based Bipolar Resistive Memories," *IEEE Trans. Nucl. Sci.*, vol. 60, pp. 4540 – 4546, Dec. 2013.

## Panasonic Embedded ReRAM



# 1T1R-ReRAM Memory Cell Resistance-change element



Function	Description
Memory Size	64 KB
Program Endurance	Program area (62 KB): ≥ 10 <sup>3</sup>
	Data area (2 KB): ≥ 10 <sup>5</sup>
Programming Voltage	1.8 to 3.6 V
Reading Voltage	1.1 to 3.6 V
Data Retention	10 years


- Panasonic MN101L
  - 16 bit microcontroller with embedded ReRAM
  - Industry's first mass production-level ReRAM
- 1T1R array architecture, with CMOS transistor as access transistor to each ReRAM stack
- TaO<sub>x</sub> as switching layer
- Minimum device width ~ 0.5 μm
  - Fabricated back-end-of-line in a 180 nm CMOS process


http://www.semicon.panasonic.co.jp/en/products/microcomputers/mn101l


ReRAM – Reduction-Oxidation Random Access Memory 1T1R – 1 transistor 1 resistor

## **Heavy Ion Testing**










Microphotograph courtesy of JPL

- Kovar lid collimator (254 μm) exposed ReRAM array and peripheral control circuits
- Used Panasonic's evaluation card as test vehicle
- ROM operating conditions: V<sub>cc</sub> = 3.3 V, Frequency = 8 MHz or DC
- Test modes: static, dynamic read, read/compare/write, and write
- Data patterns: 00, FF, 55, and AA
- 15 MeV/amu heavy ions in air at Texas A&M University
- 16 MeV/amu heavy ions in vacuum at Lawrence Berkeley National Laboratory

ROM - Read-Only Memory

## **Heavy Ion Test Results**






- No SEU from static test
  - 1 functional error following Xe irradiation, during read-back, recovered by a reset
- Dynamic read and write produced mostly SEFIs
  - 1 locked mode event
- Similar SEFI cross sections for read and write test mode
- Angular irradiation
  - Beam shadowing from the collimator likely contributed to reduced cross section

SEU – Single-Event Upset SEFI – Single-Event Functional Interrupt





#### Functional interrupts

- Microcontroller stops reading/writing
- Flash vulnerable to large scale page and block errors

#### Bit upsets

- Include single-bit and multiple-bit upsets
- Error address locations distributed throughout the microcontroller memory bank
- 8 SEUs in the ROM

http://www.semicon.panasonic.co.jp/en/products/microcomputers/mn101l

## **Pulsed-Laser Testing**




- Pulsed-laser testing was carried out at the Naval Research Laboratory
- Laser characteristics
  - Wavelength = 590 nm
  - 1/e penetration range = 2 μm in silicon
  - Beam diameter = 1.7 μm for 20× lens, 0.9 μm for 100× lens
- We probed the ReRAM array and surrounding peripheral circuits with a 20× lens to identify the sensitive regions
- Sensitive areas were further investigated with a 100× lens, and the energy was fine-tuned to determine the upset energy threshold
- Equivalent LET values are based on empirical data from previous studies on other device types

LET – Linear Energy Transfer

## **Sensitive Locations**





#### Bit upsets


- Did not originate from the ReRAM array
- Location sensitive to SEUs also susceptible to SEFIs

#### Functional interrupt

- Stops reading/writing
- Continuously reading out errors from the ROM
- Stuck reading at end of Bank0 (FFFF)
- Continuously reading errors from other address locations beside the ROM


# **Upset Sensitivity in the Most Sensitive Location**





- Determine upset energy threshold at the most sensitive location using 100× lens
- Location 1:
  - Read mode: 5.5 pJ (17 MeV·cm²/mg)
  - Write mode: 8.6 pJ (26.5 MeV⋅cm²/mg)
- Location 2:
  - Read mode: 71 pJ (220 MeV·cm²/mg)
- Location 3:
  - Read mode: 105 pJ (320 MeV·cm²/mg)






SF Register – Special function register IO Register – Input/Output register


- Compare SEE characteristics with heavy ion results
- Memory address of errors from laser test are similar to those from heavy ion test
- SEFI modes from laser and heavy ion test are also similar
  - Although limited information was gained from SEFIs that caused immediate cease of operation
- Sensitive region consists of sense amplifier circuit
  - SEU in the sensing circuit of flash devices lead to SEFI\*

<sup>\*</sup> D. Nguyen and L. Scheick, "SEE and TID of emerging non-volatile memories," in Proc. IEEE Radiation Effects Data Workshop, 2002, pp. 62-66.

## **Adesto CBRAM**








- 128 kb EEPROM from Adesto
- Ag/GeS2/W conductive bridge memory (CBRAM)
- 1T1R structure
- Back-end-of-line 130 nm CMOS

EEPROM – Electrically Erasable Programmable Read-Only Memory

### Adesto CBRAM





- Heavy ion test carried out at LBNL in vacuum
- 8-pin SOIC packages were chemically etched to expose die
- 16 MeV/nuc cocktail
- Test conditions:
  - NASA's LCDT tester
  - Vcc = 3.3 V
  - Frequency = 1 kHz or DC
  - Mode: static random read, static sequential read, continuous random read, write all/random read, write all/sequential read
  - Patterns: 00, FF, AA, and counter

LBNL – Lawrence Berkeley National Laboratory


SOIC - Small Outline Integrated Circuit

LCDT - Low Cost Digital Tester




- Static "On" and dynamic test modes produced mostly SEFIs
- Most (if not all) bit upsets due to acknowledgement fails, indicative of control circuit errors and not array errors
- SEFI modes
  - Stuck address, accumulating acknowledgement failures
    - Occurred during read and write/read test modes
    - Reset usually required
  - Read errors in continuous addresses
    - Column, page, or entire memory read out 00FF
    - Errors may clear by itself, or reset required
- No Apparent pattern sensitivity for FF, 00, AA, and Counter






Column errors (0000 to 000F) during read; memory still functional






Column errors (0000 to 00CF) during read; memory still functional





- Entire memory reading 00FF during read
- Column errors (0000 to 00CF) during read
- Stuck at single address; reset required





## Conclusion



- RRAM array immune to heavy ions with LET as high as 75 MeV·cm²/mg
  - SEU in CMOS access transistor not enough to cause bit flip
- SEFI is the dominant error mode
  - Panasonic MN101L embedded ReRAM's SEFIs originate from sense amplifier circuits
  - Adesto CBRAM showed column/page errors, mass read errors from entire memory, and stuck address errors
- Lack of charge pump reduces sensitivity to erase or program failure
  - Eliminates block erase failures (issue for flash)